


REPLACEMENT



OPERATIONAL ISSUES

LOSS OF GRASS FIELD DURING CONSTRUCTION
 NEW TEMPORARY PARKING LOT REQUIRED.
 PHASE 1 - CONSTRUCT NEW GYM AND NEW GRAVEL FIELD BEFORE DEMOLISHING OLD GYM
 PHASE 2 - CONSTRUCTION

SITE RELATIONSHIP ISSUES

EAST FACING CLASSROOMS NOT IDEAL
 GYMNASIUM IS PRIMARY MASS TO PUBLIC
 BUILDING MASS HAS POOR RELATIONSHIP TO SINGLE FAMILY RESIDENCES
 MAIN ENTRY OFF HANDSWORTH MAY CREATE TRAFFIC ISSUES / UPGRADES ON CAPILANO.
 INDUSTRIAL EDUCATION ACCESS IS DIFFICULT.
 ACCESS OFF EDGEWOOD IS NOT EFFECTIVE AS DROPOFF DUE TO GRADE ISSUE AND ENTRY POINT.

OPTION D NEW SCHOOL 3 STOREY